

CF06 - 6km function does not work

Error code	Cause	Result
CF06	6km function does not work	Walk assistance cannot work.

Troubleshooting

Step 1 Replace the controller.

Replace a new controller to see if it's controller issue.

Specification	Solution
Problem solved.	Repair complete.
Error still happen.	Go to step 2

Step 2 Replace the display.

Replace a new display to see if it's display issue.

Specification	Solution
Problem solved.	Repair complete.
Error still happen.	Go to step 3

Step 3 Replace the motor.

Replace a new motor to see if it's motor issue.

Specification	Solution
Problem solved.	Repair complete.
Error still happen.	Contact BAFANG.